Name:

Reg No.:\_

# APJ ABDUL KALAM TECHNOLOGICAL UNIVERSITY

THIRD SEMESTER B.TECH DEGREE EXAMINATION(R&S), DECEMBER 2019

Course Code: EE205

Course Name: DC MACHINES AND TRANSFORMERS													
Max	x. M	arks: 100					Duration: 3	Hours					
Graph sheets shall be provided PART A													
Answer all questions, each carries5 marks.													
1		Dummy coils are not used in lap winding. Justify with suitable example											
2		What is armature reaction? What are the effects of armature reaction on the performance of dc machine?											
3	Derive the condition for gross mechanical power developed by motor is maximum?												
4	Draw the phasor diagram of a practical transformer under no-load condition.												
Name the no-load components and write its equation.  A 11000/230V, 200kVA, 50Hz single phase transformer has core loss of 1200 V and copper loss of 1700 W at full load condition. Find the load in kVA at which maximum efficiency occurs?  What are the essential and desirable conditions to be satisfied for parall													
									6		operation of single pha	ise transform	ners?
7		What is vector grouping? Name the vector groups commonly used in three phase transformers?											
8		What is tertiary windir	ıg?					(5)					
		Answa	or anv twof	PART B	s each ca	rries 10 mai	rks.						
0	_ \		•										
9	a)	There are 60 conductor winding is preferred? core?			(5)								
	b)		e odd numb	er for simp	lex windin	ig. Why?		(2)					
			$Y_F$ should be odd number for simplex winding back pitch and front pitch of a simplex 2-lay age pitch = 6. Resultant pitch = 2			ayer lap wi	nding with 12	(3)					
1.0		coils. Average pitch = 6, Resultant pitch = 2.  The open circuit characteristics of a dc shunt generator running at 850 rpm is											
10		given below.	generator	rummig at o	oo ipin is								
		I <sub>f</sub> (A) 0	0.8	1.6	2.4	3.2	4						
		Emf (V) 0	28	57	76	90	100						
		Calculate				A							
		i. emf to which the n											
		ii. emf when an additional resistance of $8\Omega$ is included in the shunt field circuit iii. shunt field resistance for a normal voltage of $100V$											
		iv. Critical speed with shunt field resistance for a voltage of 100V											
11	a)	What is equalizer rings windings?						(5)					
	b)	A long shunt compour five motors each draw The armature, series	ving 60A ai	nd a lightin	g load of	250 lamps	at 100W each.	(5)					

respectively. Find (i) load current (ii) armature current (iii) emf generated.

#### PART C

## Answer any two full questions, each carries 10 marks.

- 12 a) Explain the characteristics curves of a dc series motor with the help of relevant equations?
  - b) Why transformer rating is in kVA and not in KW?
- A 250V dc shunt motor takes 5A on no-load. The armature and field resistances are  $1\Omega$  and  $125\Omega$  respectively. Find its efficiency when it takes a line current of 25A. (10)

The OC and SC test results of a 5kVA, 200/400V, 50Hz single phase transformer is as follow.

	OC Test		SC Test			
$V_1(V)$	I <sub>1</sub> (A)	W <sub>1</sub> (W)	V <sub>2</sub> (V)	I <sub>2</sub> (A)	$W_2(W)$	
220	0.7	60	22	10	120	

Draw the equivalent circuit of transformer as referred to low voltage side.

(10)

(5)

(5)

(5)

#### PART D

## Answer any twofull questions, each carries 10 marks.

- Draw the circuit diagram of Sumpner's test and derive the equation for efficiency of each transformer? (5)
  - b) Explain how the Scott connection can be used to obtain two phase supply from a three phase supply? (5)
- The primary and secondary voltages of an autotransformer are 1200V and 600V respectively. Calculate the economy of Cu when the secondary current is 120A.

  Draw the circuit and show the current distribution in the winding.
  - b) Define all day efficiency of transformer. Why this efficiency is less than commercial efficiency? (5)
- 17 a) A 10 kVA, 200/400V, 50Hz single phase transformer gave the following result.

O.C test: 200V, 1.3A, 120W ......on L.V side

S.C test: 22V, 30A, 200W ......on H.V side

- Calculate (i) the magnetising current and the component corresponding to core loss at normal frequency (ii) the magnetising branch impedances.
- b) With the aid of three phase transformer connections and phasor diagram, explain the vector group Dyl1.

